



**5020 Old Ellis Point - Suite 200
Roswell, Georgia 30076
WWW.Genesisshocks.com**

**678-659-9454
Fax - 678-659-9457
E-mail - info@Genesisshocks.com**

Gas Filler Tool

USE DRY AIR OR NITROGEN ONLY. NEVER USE OXYGEN OR ANY FLAMMABLE GAS

Your gas filler tool gauge has a input pressure limit, in pounds per square inch (PSI), that is indicated by the highest number on the face of the gauge. Exceeding this limit will permanently damage the gauge and could burst, causing injury or death. Permanent damage from over pressure is indicated by the needle no longer returning to zero. **This not a warranty condition.**



**5020 Old Ellis Point - Suite 200
Roswell, Georgia 30076
WWW.Genesisshocks.com**

**678-659-9454
Fax - 678-659-9457
E-mail - info@Genesisshocks.com**

Gas Filler Tool

USE DRY AIR OR NITROGEN ONLY. NEVER USE OXYGEN OR ANY FLAMMABLE GAS

Your gas filler tool gauge has a input pressure limit, in pounds per square inch (PSI), that is indicated by the highest number on the face of the gauge. Exceeding this limit will permanently damage the gauge and could burst, causing injury or death. Permanent damage from over pressure is indicated by the needle no longer returning to zero. **This not a warranty condition.**